

Date: Wednesday, 16/05/2007 12:44:02 PM
 User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: K10018 (D2174-041)
Job Number	: 32425		
Estimate Number	: 10804		
P.O. Number	: N/A	Part Number	: K10018
This Issue	: 16/05/2007 S.O. No. : N/A	Drawing Number	: REMOVE FROM STK
Prsht Rev.	: NC	Project Number	: N/A
First Issue	: N/A Type : SMALL /MED FAB	Drawing Revision	: N/A
Previous Run	: 00015	Material	: N/A
Written By	:	Due Date	: 23/05/2007
Checked & Approved By	:	Qty:	2 Um: Each
Comment	:		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

REMOVE FROM STK

2 X K10018 B 1X B2893/

1X 29019

2.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

REMOVE 2 X D2174-041'S FROM EACH KIT

D2174-041 B 29225

REQ'D FOR K10021

3.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

RETURN D2174-041 B _____
 TO KITS WHEN AVAILABLE
 REPACKAGE PER PPP
 USING NEW B/N

B 31651 4X

6/7/16 (2)

Date: Wednesday, 16/05/2007 12:44:02 PM
User: Linda Lacelle

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: K10018 (D2174-041)

Job Number: 32425

Part Number: K10018

Job Number:



Seq. #:

Machine Or Operation:

Description :

4.0

QC21

FINAL INSPECTION/W/O RELEASE



@

Comment: FINAL INSPECTION/W/O RELEASE

20070610

Job Completion



U 07-0607